

**ADDENDUM NO. 3**

**Date:** March 6, 2024

**To:** All Bidders

**Reference:** Pre-Bid Conference Meeting Minutes  
Bolivia Elementary School  
Roof Replacement  
Bolivia, North Carolina  
SKA Job No. 230443.0

The contractor shall consider the following clarifications, modifications, and general items described herein when preparing and submitting bids for the referenced project. All associated costs for items described herein shall be included in the contractor's bid.

**General**

1. Asbestos Report: The asbestos report refers to the administration building, gym and music building. The building designations on the drawings are as follows:

Administration Building      Roof Area D and E

Gym      Roof Area J

Music Building      Roof Area I

2. Clarification: All roof areas are to have a minimum two layers of insulation that match the thickness call on in the table on Sheet R2.1. The base layer (ie bottom/first layer) of insulation is to be mechanically attached to the roof deck as specified. The subsequent layer (ie second layer) and any tapered or cricket insulation is to be adhered as specified.

Submitted by:

SKA CONSULTING ENGINEERS, INC



Brian D. Cuthbertson  
Building Solutions Group